



PHOTOGRAPH No.13. Communication Station



PHOTOGRAPH No.14. View looking SW over car park - Perisher



PHOTOGRAPH No.15. Visitor Centre at North end of Workshop



PHOTOGRAPH No.16. Example of scattered car parking (poor surface condition)



PHOTOGRAPH No.17. Lock up section of car park (for Lodge Managers)



PHOTOGRAPH No.18. Another view of scattered car parking (poor surface condition)