



PHOTOGRAPH No.37. Cooking oils can storage.



PHOTOGRAPH No.38. Groundwater monitoring around current Landfill



PHOTOGRAPH No.39. Leachate primary settling pond (plastic lined)



PHOTOGRAPH No.40. Secondary settling pond (unlined)



PHOTOGRAPH No.41. Current landfill – no evidence of daily soil cover



PHOTOGRAPH No.42. Kosciuszko Road (good section – sealed to edge & fenced.