



PHOTOGRAPH No.48. Road adjacent to Smiggin Holes workshop (summer track)



PHOTOGRAPH No.49. Kosciuszko Road – unsealed shoulder – effect of snow blowing on adjacent snow.



PHOTOGRAPH No.50. Gravel / dirt on snow alongside road and in creek from snow blowing.



PHOTOGRAPH No.51. Another view of the contamination alongside road from snow blowing.



PHOTOGRAPH No.52. Entrance to Perisher Village



PHOTOGRAPH No.54 Entrance to Perisher Village (PBL resort in background)