

SRV APPLICATION ATTACHMENT S
Timber Bridge Conditions Map

State Forest
National Park

Bridge Condition Legend

- Severity - Major (Unsafe condition/Closure or immediate repair) - No (7)
- Severity - Intermediate (Severely decayed, 5 Tonne load limit signage required) - No (4)
- Severity - Moderate (Deteriorated, 35-60% Load limits 7-12 Tonnes bogie loads) - No (5)
- Severity - Minor (64-75% Load Limits/13-16 Tonnes bogie loads) - No (9)
- Short Term Adequate (Capable to carry full mass limit traffic, some rehabilitation within 6-24 months) - No (17)
- Satisfactory (Capable to carry full mass limit traffic) - No (43)

Clarence Valley Council

Coffs Harbour City Council

Kempsey Shire Council

Nambucca Shire Council

