



PHOTOGRAPH No.19. Scattered line of cars – no line marking



PHOTOGRAPH No.20. View looking South of car park (line marking just visible here)



PHOTOGRAPH No.21. Tag system at Thredbo



PHOTOGRAPH No.22. Close up of rubbish tag system



PHOTOGRAPH No.23. Mountains West of Thredbo



PHOTOGRAPH No.24. Mountains West of Thredbo (snow melting)