



PHOTOGRAPH No.25. Car park condition at Smiggin Holes (looking toward workshop)



PHOTOGRAPH No.26. Smiggin Holes workshop (open petrol pump and contamination of asphalt)



PHOTOGRAPH No.27. Gate entry to KNP on Kosciuszko Road



PHOTOGRAPH No.28. Gate entry / exit on Kosciuszko Road



PHOTOGRAPH No.29. Gate entry / Exit on Kosciuszko Road



PHOTOGRAPH No.30. Sawpit Creek Landfill site